

SECTION 1 – INITIATION OF REQUEST

DATE:	3SEP2024	BULLETIN #	RL-09.03.2024	REVISION:	1
KIT #:	66-21300 66-21320	PART #:	67-21350UCAL 67-21350UCAR	QUANTITY:	1,170
BRAND:	READYLIFT	DESCRIPTION:	RL 3" FRONT LIFT FORD F-150 TREMOR		
P/N HARMS CLASIFICACION	X 1 (Safety Critical) <input type="checkbox"/> 2 (Moderate) <input type="checkbox"/> 3 (Minor)				
INCIDENT CLASIFICACION	X 1 (Safety Critical) <input type="checkbox"/> 2 (Moderate) <input type="checkbox"/> 3 (Minor)				
DESCRIPTION OF PROBLEM:	Some customers may experience damage to the ball joint housing as a result of extreme driving.				

SECTION 2 – RECEIPT

X MANUFACTURING	X ENGINEERING	X QUALITY	X CSR
-----------------	---------------	-----------	-------

SECTION 3 – REASON & DISPOSITION OF PARTS

SUGGESTED SOLUTION:	ReadyLIFT will provide upgraded replacement parts to customer at no charge.
PARTS:	67-21640UCAL – RL UCA ASSM, LFT (QTY. 1) 67-21640UCAR – RL UCA ASSM, RHT (QTY. 1) 90-60801 - UCA WSHR M12 TAPERED (QTY. 2) 90-60835 - HWPK 1-1/4 ADEL CLAMP (QTY. 2)
TEST:	Engineering has performed testing to assure upgraded upper control arm assemblies perform as designed under extreme conditions.

Please contact our Customer Service Tech Department at (800)-549-4620. They will be able to assist you with any questions you may have regarding this issue.

READYLIFT SUSPENSION
1017 W. 600 N. SUITE 4
OGDEN, UT. 84404
TOLL FREE: (800)-549-4620

SECTION 4 – VISUAL REPRESENTATION OF THE FIX

SUSPECT ARMS DO NOT HAVE CAPS OR SIDE-SPECIFIC DECALS



Before TSB

UPGRADED ARMS HAVE BALL JOINT CAPS AND SIDE-SPECIFIC DECALS



After TSB

READYLIFT SUSPENSION
1017 W. 600 N. SUITE 4
OGDEN, UT. 84404

TOLL FREE: (800)-549-4620 Please contact our Customer Service Tech Department at (800)-549-4620. They will be able to assist you with any questions you may have regarding this issue.